



Figure 3C-6.
Areas Inundated during Channel
Maintenance Flows - Rush Creek
Bottomlands

Sources:
Inundation areas from aerial photography on 6-19-91 with
Mono Gate #1 release of 161 cfs.

Topography from photogrammetry by Aerial Photometrics
from 5-6-91 photographs; original contour interval is 2 feet.