Table P-10. Responses to Rewatering Observed in Mature Woody Riparian Vegetation on Parker Creek in 1991

Response Level/ Vegetation Type	Reach Number				
	1	2	3	4	All Reaches
No response					
Conifer-broadleaf	0.8			0.3	1.1
Cottonwood-willow					
Aspen	0.2				0.2
Willow scrub	2.4	9.7	0.5		12.6
Mixed riparian	0.2	0.2		0.9	1.3
All types	3.6	9.9	0.5	1.2	15.2
Percent of total mapped	24%	32%	100%	55%	31%
Slight response					
Conifer-broadleaf		0.3			0.3
Cottonwood-willow		0.2			0.2
Aspen					
Willow scrub	5.0	20.1			25.1
Mixed riparian	0.3	0.2		1.0	1.5
All types	5.3	20.8		1.0	27.1
Percent of total mapped	35%	67%		45%	55%
Moderate response					
Conifer-broadleaf					
Cottonwood-willow					
Aspen					
Willow scrub	6.3				6.3
Mixed riparian					
All types	6.3				6.3
Percent of total mapped	41%				13%
Strong response					
All types					
Percent loss or gain					

Notes: See Appendix F for explanation of response categories.

Reach 1 = diversion to foot of moraine.

Reach 2 = foot of moraine to Cain Ranch Road.

Reach 3 = Cain Ranch Road to U.S. 395.

Reach 4 - U.S. 395 to Rush Creek.

Percentages may not total 100% because of rounding error.

Acreages measured by Jones & Stokes Associates from interpretation of 1929-1930, 1940, and 1990 aerial photographs and 1990-1991 field surveys.